

# **ASPHALT & LIMEROCK THICKNESS REPORT**

## ***CONDUCTED AT:***

Creeside Corners @ Creekside East  
Goodlette-Frank Road & Parking Lot  
Naples, Collier County, Florida

## ***PREPARED FOR:***

Mr. Chris Gehring  
Project Manager  
Earth Tech Enterprises, Inc.  
5475 Golden Gate Pkwy.  
Naples, Florida 34116-7529

7 December 2015  
YPC Project No.: 15CY586  
Lab No.: 1AC



***YPC Consulting Group, PL  
5931 Country Lakes Drive  
Fort Myers, Florida 33905  
Phone (239) 693-7700  
Fax (239) 690-0271***



YPC Consulting Group, P.L.  
5931 Country Lakes Drive  
Fort Myers, Florida 33905  
Phone (239) 693-7700  
Fax (239) 690-0271  
Florida Certificate of Authorization No. 28233

Mr. Chris Gehring  
Project Manager  
Earth Tech Enterprises, Inc.  
5475 Golden Gate Pkwy.  
Naples, Florida 34116-7529

7 December 2015

**Subject:**        *Asphalt & Limerock Thickness Report  
Goodlette-Frank Road, Parking Lot  
Creekside Corners @ Creekside East.  
Naples, Collier County, Florida  
YPC Project No.: 15CY586  
Lab No: 1AC*

Dear Mr. Gehring:


On 7 December 2015, **YPC Consulting Group, P.L. (YPC)** has completed coring services to determine the thickness of asphalt surface course and base course at the above-referenced project site. Thicknesses were determined at a total of seven (7) locations along the referenced roadway alignments. Thicknesses of the asphalt surface course and base at core locations are summarized in the *Asphalt & Limerock Thickness Report* presented in **Attachment 1**.

Please contact us should you have any questions regarding this report or if you require additional information.

*Sincerely,*

*YPC Consulting Group, P.L.*

Hiram F. Murati, P.E.  
Senior Project Manager  
Florida Registration No. 44599



attachments: **Attachment 1 - Asphalt & Limerock Thickness Report**

Chris Gehring: [cg@earthtechenterprises.com](mailto:cg@earthtechenterprises.com)

Lisa Gehring: [lisa@earthtechenterprises.com](mailto:lisa@earthtechenterprises.com)

- 
- |   |  |
|---|--|
| • <b>Geotechnical Engineering</b>       | • <b>Pre-Condition Surveys</b>         |
| • <b>Construction Materials Testing</b> | • <b>Threshold Inspection Services</b> |
| • <b>Pile Monitoring Services</b>       | • <b>Vibration Monitoring Services</b> |

# ATTACHMENT 1

## ASPHALT AND LIMEROCK THICKNESS REPORT

***YPC Consulting Group, P.L.  
5931 Country Lakes Drive  
Fort Myers, Florida 33905***

**(239) 693-7700 phone**

**(239) 690-0271 fax**

***Certificate of Authorization No. 28233***

<b>PROJECT:</b>	Creekside Corners @ Creekside East	<b>DATE:</b>	7-Dec-15		
<b>LOCATION:</b>	Immokalee & Goodlette Frank Road, Naples, Florida	<b>PROJECT:</b>	15CY586		
		<b>LAB NO.:</b>	1-AC		
<b>CLIENT:</b>	Earth Tech Enterprises, Inc.	<b>CORE DATE:</b>	12/7/15		

[illegible]